



Load Test Result 1701 Lid

Vertical Load Test Report

| | | |
|---|---|--------------------------------|
| Factory Production Control Manual | Version No.: 002 | PR/PR/REV001/RJM/07.09.2020 |
| 1701 Duct Lid | | Form QS9 Rev002/RJM/EPC/June16 |
| Dimensional Checks  <p>Tolerances : Thickness not less than normal $\pm 5.0\text{mm}$</p> | Date Made: 10/01/2022 Date Tested: 18/02/2022 Test Age: 5-6 weeks Bedding Condition: OK Age of the Bed: 4 Days Proof load applied (Fp): 400 KN Residual crack width (max. 0.15mm): N/A Collapse Load (Fu) (cover and ITT only) (min 300kN) 400 KN: No Failure Visual appearance (cracks or surface voids): 0 Acceptable | |
| Vertical Load Test Arrangement  | | |
| Tested By : S.Savigar | | Result (PASS/FAIL): PASS |

